



B=	2500	3000	3500	4000	4500	5000	5500	6000	6500	7000	7500	8000	8500	9000	9500	10000	10500	11000	11500	12000	12500
G=	700	850	1000	1050	1150	1360	1360	1360	2000	2150	2300	2450	2500	2500	2600	2600	3170	3320	3480	3600	3800
F=	3710	4360	5010	5560	6160	6870	7370	7870	9010	9660	10310	11000	11510	12010	12610	13110	14180	14830	15490	16110	16810
E=	1200	1350	1500	1550	1650	1860	1860	1860	2500	2650	2800	2950	3000	3000	3100	3100	3670	3820	3980	4100	4300
U=	1120	1270	1420	1470	1570	1780	1780	1780	2420	2570	2720	2870	2920	2920	3020	3020	3590	3740	3900	4020	4220
K=	2550	3050	3550	4050	4550	5050	5550	6050	6550	7050	7550	8050	8550	9050	9550	10050	10550	11050	11550	12050	12550
D=	2280	2780	3280	3780	4280	4780	5280	5780	6280	6780	7280	7780	8280	8780	9280	9780	10280	10780	11280	11780	12280
Z=						2650	2900	3150	3400	3650	3900	4150	4400	4650	4900	5150	5400	5650	5900	6150	6400
A=	3790	4440	5090	5640	6240	6950	7450	7950	9090	9740	10390	11080	11590	12090	12690	13190	14260	14910	15570	16190	16890

Maßangaben ohne Gewähr

